



AD-A139 201 SURVEILLANCE REPORT STAGE I DISSECTED MOTORS PHASE XIV 1/2
PROPELLANT AND COM..(U) OGDEN AIR LOGISTICS CENTER HILL
AFB UT PROPELLANT ANALYSIS LA.. J A THOMPSON DEC 83
UNCLASSIFIED MANPA-482(83) F/G 21/9.2 NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS 1963 A

AD A139201

HEADQUARTERS

OGDEN AIR LOGISTICS CENTER

UNITED STATES AIR FORCE

HILL AIR FORCE BASE, UTAH 84056

SURVEILLANCE REPORT
STAGE I
DISSECTED MOTORS
PHASE XIV

PROPELLANT ANALYSIS LABORATORY

MANPA REPORT NR
482(83)

DECEMBER 1983

DTIC
ELECTE
MAR 21 1984

APPROVED FOR PUBLIC RELEASE, DISTRIBUTION UNLIMITED

DTIC FILE COPY

84 03 21 077

SURVEILLANCE REPORT
STAGE I DISSECTED MOTORS
PHASE XIV PROPELLANT & COMPONENT TESTING

Author

John A. Thompson
JOHN A. THOMPSON, Chemist
Component and Combustion Test Unit

Engineering & Statistical Review By

John K. Scambia
JOHN K. SCAMBIA, Project Engineer
Service Engineering

Edward J. Erickson
EDWARD J. ERICKSON, Statistician
Data Analysis Unit

Recommended Approval By

Dan L. Petersen
DAN L. PETERSEN, Chief
Propellant & Analysis Test Units

Approved By

Anthony J. Inverso
ANTHONY J. INVERSO, Chief
Propellant Analysis Laboratory

December 1983



A1

Ind Products & Ldg Gear Division
Directorate of Maintenance
Ogden Air Logistics Center
United States Air Force
Hill Air Force Base, Utah 84056

ABSTRACT

Testing was performed to determine the useful shelf/service life for LGM-30 Stage I Rocket Motors. A three year storage program for propellant and components was started in May 1961. This program was then extended to a ten year study and later continued indefinitely to assure that a deterioration in motor physical characteristics could be detected in time to take some corrective actions before the weapon system performance deteriorated below an acceptable level.

This report covers only propellant data and limited case bond data. The malfunction of an environmental chamber destroyed component samples that had originally been part of this testing program (and the inadvertent burning of some motors during dissection reduced the material available for testing). Planned dissection of selected motors in the future will provide samples for continued component testing. Test specimens for this reporting period were obtained from motors STM-012, 0012099, and 0012199. UP-7775 block propellant was not tested since that propellant has been used up.

A new technique of Multi-symbol Regression Analysis was used to determine aging trends. Also, using a unique plotting code for each motor tested demonstrates the relationship between motors and block propellant. The plotting symbols for each motor and block propellant are listed in the statistical analysis section.

The data from this test period was combined with data from previous testing and entered into the GO85 computer for storage, analysis, and regression analysis. From the statistical analysis of all data tested to date, significant degradation of the propellant does not appear likely for at least two years past the oldest data point.

Future testing will be conducted on dissected motors.

TABLE OF CONTENTS

	<u>Page</u>
Abstract	ii
List of Figures	iv
Glossary of Terms and Abbreviations	ix
Introduction	1
Statistical Analysis	3
Table 1, Test Program	5
Test Results	6
Discussion of Test Results	11
Table 2, Analysis of Covariance	12
Table 3, Regression Trend Line Summary	13
Distribution List	108
DD1473	109

LIST OF FIGURES

<u>Figure Nr</u>		<u>Page</u>
Regression Plot, Low Rate Tensile, 2.0 in/min		
1	Strain at Max Stress, Combined Motors	15
1-A	Strain at Max Stress, Motor 0012099	16
1-B	Strain at Max Stress, Motor 0012199	17
1-C	Strain at Max Stress, Motor STM-012	18
2	Maximum Stress, Combined Motors	19
3	Strain at Rupture, Combined Motors	20
3-A	Strain at Rupture, Motor 0012099	21
3-B	Strain at Rupture, Motor 0012199	22
3-C	Strain at Rupture, Motor STM-012	23
4	Stress at Rupture, Combined Motors	24
5	Modulus, Combined Motors	25
Regression Plot, Low Rate Tensile, 20.0 in/min		
6	Strain at Max Stress, Combined Motors	26
6-A	Strain at Max Stress, Motor 0012099	27
6-B	Strain at Max Stress, Motor 0012199	28
6-C	Strain at Max Stress, Motor STM-012	29
7	Maximum Stress, Combined Motors	30
7-A	Maximum Stress, Motor 0012099	31
7-B	Maximum Stress, Motor 0012199	32
7-C	Maximum Stress, Motor STM-012	33
8	Strain at Rupture, Combined Motors	34
8-A	Strain at Rupture, Motor 0012099	35
8-B	Strain at Rupture, Motor 0012199	36
8-C	Strain at Rupture, Motor STM-012	37
9	Stress at Rupture, Combined Motors	38

LIST OF FIGURES (cont)		
<u>Figure Nr</u>		<u>Page</u>
10	Modulus, Combined Motors	39
	Regression Plot, High Rate Tensile	
11	Strain at Max Stress, Combined Motors	40
12	Maximum Stress, Combined Motors	41
13	Strain at Rupture, Combined Motors	42
14	Stress at Rupture, Combined Motors	43
15	Modulus, Combined Motors	44
	Regression Plot, High Rate Triaxial Tensile, 600 psi	
16	Strain at Max Stress, Combined Motors	45
17	Maximum Stress, Combined Motors	46
18	Strain at Rupture, Combined Motors	47
19	Stress at Rupture, Combined Motors	48
20	Modulus, Combined Motors	49
	Regression Plot, Casebond Tensile	
21	Maximum Stress, Combined Motors	50
21-A	Maximum Stress, Motor 0012199	51
21-B	Maximum Stress, Motor STM-012	52
	Regression Plot, Creep, 10 lb Load	
22	Compliance at 10 sec	53
23	Compliance at 20 sec	54
24	Compliance at 1000 sec	55
25	Compliance at 10,000 sec	56
	Regression Plot, Creep, 12 lb Load	
26	Compliance at 10 sec	57
27	Compliance at 20 sec	58
28	Compliance at 1000 sec	59
29	Percent Strain at Rupture	60

LIST OF FIGURES (cont)

<u>Figure Nr</u>		<u>Page</u>
Regression Plot, Stress Relaxation Modulus, 3% Strain		
30	10 sec	61
31	50 sec	62
32	100 sec	63
33	1000 sec	64
Regression Plot, Stress Relaxation Modulus, 5% Strain		
34	10 sec	65
35	50 sec	66
36	100 sec	67
37	1000 sec	68
Regression Plot, Constant Strain		
38	Strain at Rupture, Combined Motors	69
38-A	Strain at Rupture, Motor 0012199	70
38-B	Strain at Rupture, Motor STM-012	71
Regression Plot, Hardness		
39	10 sec, Combined Motors	72
39-A	10 sec, Motor 0012099	73
39-B	10 sec, Motor 0012199	74
39-C	10 sec, Motor STM-012	75
Regression Plot, Dynamic Response		
40	Loss Tangent at 200 HZ	76
41	Loss Tangent at 400 HZ	77
42	Storage Shear Modulus at 200 HZ	78
43	Storage Shear Modulus at 400 HZ	79
Regression Plot, Sol Gel		
44	Percent Extractables	80

LIST OF FIGURES (cont)

<u>Figure Nr</u>		<u>Page</u>
45	Weight Swell Ratio	81
46	Density	82
47	Crosslink Density	83
Regression Plot, Burning Rate		
48	500 psi, Combined Motors	84
48-A	500 psi, Motor 0012099	85
48-B	500 psi, Motor 0012199	86
48-C	500 psi, Motor STM-012	87
49	1000 psi, Combined Motors	88
49-A	1000 psi, Motor 0012099	89
49-B	1000 psi, Motor 0012199	90
49-C	1000 psi, Motor STM-012	91
Regression Plot, Heat of Explosion		
50	Combined Motors	92
50-A	Motor 0012099	93
50-B	Motor 0012199	94
50-C	Motor STM-012	95
Regression Plot, DTA		
51	Endotherm 1, Combined Motors	96
51-A	Endotherm 1, Motor 0012099	97
51-B	Endotherm 1, Motor 0012199	98
51-C	Endotherm 1, Motor STM-012	99
52	Exotherm 1, Combined Motors	100
52-A	Exotherm 1, Motor 0012099	101
52-B	Exotherm 1, Motor 0012199	102
52-C	Exotherm 1, Motor STM-012	103
53	Ignition Temperature, Combined Motors	104

LIST OF FIGURES (cont)

<u>Figure Nr</u>		<u>Page</u>
53-A	Ignition Temperature, Motor 0012099	105
53-B	Ignition Temperature, Motor 0012199	105
53-C	Ignition Temperature, Motor STM-012	107

GLOSSARY OF TERMS AND ABBREVIATIONS

Aging Trend	A change in properties or performance resulting from aging of material or component
CSA	Cross Sectional Area
DB	Dogbone
Degradation	Gradual deterioration of properties or performance
E	Modulus (psi), defined as stress divided by strain along the initial linear portion of the curve.
EB	End Bonded
EGL	Effective Gage Length
em	Strain at maximum stress
er	Strain at rupture
"F" ratio	The ratio of the variance accounted for by the regression function to the random unexplained variance. The regression function having the most significant "F" ratio is used for plotting data. The ratio is also used in detecting significant changes in random variation between succeeding time points
JANNAF	Joint Army, Navy, NASA, Air Force Committee
MANPA	Propellant Lab Section at Ogden Air Logistics Center
Ogden ALC	Ogden Air Logistics Center, Air Force Logistics Command
r or R	The Correlation Coefficient is a measure of the degree of closeness of the linear relationship between two variables
Regression Equation	The general form of the regression equation is $Y = a + bx$
Regression Line	Line representing mean test values with respect to time
S_b	Standard error of estimate of the regression coefficient

GLOSSARY OF TERMS AND ABBREVIATIONS (cont)

S_e or $S_{Y.X}$	Standard deviation of the data about the regression line
S_m	Maximum Stress
S_r	Stress at rupture
Standard Deviation (S_y)	Square root of variance
Strain Rate	Crosshead speed divided by the EGL
"t" test	A statistical test used to detect significant differences between a measured parameter and an expected value of the parameter (determines if regression slope differs from zero at the 95% confidence level)
Variance	The sum of squares of deviations of the test results from the mean of the series after division by one less than the total number of test results
3 Sigma Band	The area between the upper and lower 3 sigma limit. It can be expected that 99.73% of the inventory represented by the test samples would fall within this range assuming that the population is normally distributed.
90-90 Band	It can be stated with 90% confidence that 90% of the inventory represented by the test samples would fall within this range assuming that the population is normally distributed

INTRODUCTION

A. PURPOSE:

This report contains test data from samples of LGM-30 Stage I, Wings I-V TP-H1011 propellant and case bond specimens. Testing was performed by the Propellant Analysis Laboratory (MANPA) for the Engineering and Reliability Branch of the Airmunitions Management Division (MMWRM) under Project M34929C. This report is the fourteenth in this series. Data from this test period and propellant test data from the thirteen previous reports were entered into the GO85 computer for regression analysis. The regressions are shown in this report.

B. TEST PROGRAM:

The LGM-30 laboratory and component program includes the testing of materials used in the main case and main grain propellant. Table 1 outlines the test program.

Propellant for testing was obtained from three dissected motors; STM-012, a motor prepared by Thiokol specifically for dissection, S/N 0012099, a SLIM motor and S/N 0012199 which was selected for dissection.

C. HISTORICAL BACKGROUND:

In May 1961, Thiokol began a three year LGM-30 laboratory storage and test program to determine the rate of degradation with age for Stage I materials. During June 1962 and again in August 1963, additional samples were included. New samples were added in July and August 1964 when the surveillance test program was extended to ten years (Test Plan 0717-62-0967, 53-8). The samples added to the inventory in 1964 were considered to be a new population, but were combined in regression analysis with the three dissected motors.

The history of testing of these materials is found in MQQP Report Nrs. 109A(67), 144(68), 208(71) and MANCP Report Nr. 358(76). Physical transfer of the specimens from Thiokol to Ogden ALC was made in June 1967.

Until 1982, due to a limited number of dissected motor samples, data from all motors were combined for statistical analyses. In 1982, key LRSLA parameters were also reported for the individual motors (MANPA Report Nr. 470(82)). The statistical approach for this report is the same as in report 470(82).

For the next test phase all motors will be reported individually with no combined data grouped together. For motors STM-012 and 0012099, the next report will be the final report. Only motor 0012199 has sufficient assets for continued testing.

STATISTICAL ANALYSIS

The objective of this statistical analysis was to determine whether or not any aging trends are demonstrated by accumulated test data in order to assist Service Engineering to more accurately predict motor serviceability.

Propellant was made available for testing and statistical analysis was performed on the resultant data in order to obtain an overall view of the aging trends affecting the Stage I Dissected Motor Program. The sampling consisted of data from two dissected operational motors (0012099 and 0012199), and one motor (STM-012) was prepared by Thiokol specifically for the dissection program. By using TP-H1011 propellant from Stage I Dissected Motors, a normal distribution population was assumed and the data from these motors were statistically combined.

A new technique of Multi-symbol Regression Analysis Program was used to determine aging trends. The sampling is combined for each test parameter in a single regression analysis. The linear equation ($Y = a + bX$) was found to be the best fit model for the data in this report. A composite population aging regression trend line is then calculated.

The Multi-symbol program uses a unique plotting code for each motor data on the regression plots. The method of data plotting allows a visual display of the overall relationship between different motors and how they relate to the overall least square aging trend line.

The regression program uses an analysis with individual data points from different time periods combined to establish a least squares aging trend line for the overall data. The variance about the regression line, obtained using individual values of the dependent variable, was used to compute a tolerance interval such that at the 90% confidence level 90% of the population falls within this interval. This tolerance interval was

extrapolated to a maximum of 24 months to give an indication of the statistical significance of the slope of any aging trends. The computer tolerance interval about the composite regression line is wider than what the tolerance interval would be about any individual motor regression line because of the increased data spread introduced by combining different motors. The 't' values and the significance of this statistic, which are reported for each regression model, gives an indication of the "statistical significance" of the slope of the aging trend in the Y-axis. Data and regression trend lines were plotted utilizing an IBM-4341 computer.

A motor-to-motor regression comparison was performed using the Analysis of Covariance (Table 2). The key LRSLA properties being tracked in the surveillance program were selected for this test. None of the 14 tests were significantly equal. The data from these motors should not be statistically combined since they have been biased differently at some point in time. Table 3 shows an abnormal difference visually displayed through the use of multi-symbol plotting of the three different motors. The comparisons indicate no homogeneity of variance between motors. A decreasing regression trend line for motor 0012199 visually seems to be present.

ORIGIN SYMBOL TABLE

<u>Origin</u>	<u>DOM</u>	<u>Wing</u>	<u>Symbol</u>
0012099	63166	2	0
0012199	63227	2	1
STM-012	61221	1	S

TABLE 1
TEST PROGRAM

<u>Test</u>	<u>Conditions</u>	<u>Config- uration</u>	<u>Nr Specimen</u>	<u>Total Specimens</u>
Tensile , Low Rate	77°, 2 & 20 in/min	JANNAF Dogbone	5	40
Creep	77°, 10 & 12 lb Load	JANNAF Dogbone	3	24
Stress Relaxation	77°, 3 & 5% Strain	1/2"x1/2"x4"	3	24
Hardness	77°, Init & 10 sec	Dogbone Ends	5	40
HOE	77°	1/2"x3/8"x1"	5	40
DTA	77° Start	0.040" Wafers	3	12
Sol Gel	77°	1/2"x1/2"x1/2"	6	24
High Rate Tensile	77°, 1000 in/in/min	3/4" GL Dogbone	5	15
Triaxial High Rate	77°, 1000 in/in/min	3/4" GL Rail	3	9
Dynamic Response	77°, 70 gm ct.wt.	3.3"x.33"x.690" disc	3	9
Biaxial Constant Strain	77°	3/4" GL Rail	3	9
<u>Motors STM-012 and 0012199 only will be for the following tests:</u>				
Case Bond Tensile	77°, 0.2 in/min	1"x5/8"x3/4"	10	20
Tear Energy	77°F ± 2°	0.1"x1.18"x3"	8	16
Poisson's Ratio (Strain Dilatation) 10, 15, 20, 25, 30%	77°F ± 2°	0.50"x0.50"x4"	6	30

TEST RESULTS

Regression analysis is the method of evaluation used in the analysis of the test results. Regressions with the three motors combined (STM-012, 0012099 and 0012199) are presented as in previous reports. In addition, regressions for the separate motors are also presented in this report and previous report 470(82) for the testing that is also in the LRSLA program.

A. TENSILE:

1. Low Rate Tensile (2.0 in/min):

The strain at maximum stress regression (figure 1) for the combined group of all three motors shows a non-significant trend line slope. The regression trend lines for the individual motors, 0012099 (figure 1A) and STM-012 (figure 1C) show non-significant slopes. However, the individual trend line slope for motor 0012199 (figure 1B) shows a significantly decreasing trend line slope.

The strain at rupture regression (figure 3) for the combined group of all three motors shows a non-significant trend. The regression trend line for motor 0012099 (figure 3A) also shows a non-significant slope. However, the individual trend line slopes for motors 0012199 (figure 3B) and STM-012 (figure 3C) show a statistically significant negative trend.

Maximum stress (figure 2), stress at rupture (figure 4), and modulus (figure 5) for the combined group of all three motors show a non-significant trend line slope.

2. Low Rate Tensile (20.0 in/min):

The strain at maximum stress regression (figure 6) for the composite of all three motors shows a significant negative trend line slope. The regressions for the individual motors 0012099 (figure 6A) and 0012199 (figure 6B) show negative trends. The individual trend line for motor

STM-012 (figure 6C) is not significant.

The maximum stress (figure 7) for the composite group is not significant. Maximum stress for motors 0012099, 0012199 and STM-012 all show a statistically significant increase (figures 7A, 7B and 7C). Strain at rupture (figure 8) for the composite group shows a significant decreasing trend. Motors 0012099 (figure 8A) and 0012199 (figure 8B) also indicate a trend in the negative direction. However, motor STM-012 (figure 8C) has a non-significant slope. Stress at rupture (figure 9) and modulus (figure 10) composite trend lines show a statistically significant decreasing and increasing trend respectively.

3. High Rate Tensile (1000 in/min CHS):

No significant slope direction is shown for the high rate composite regressions (figures 11 thru 15).

4. High Rate Triaxial Tensile (1000 in/min, CHS 600 psi):

The composite regressions for strain at maximum stress (figure 16), strain at rupture (figure 18) and stress at rupture (figure 19) show a statistically significant increase. The composite regression for maximum stress (figure 17) has a non-significant trend line. Modulus (figure 20) shows a trend line with a decreasing slope in the negative direction.

5. Case Bond Tensile:

The composite regression for motors 0012199 and STM-012 (figure 21) and the individual regression for motor STM-012 (figure 21B) show negative trend line slopes. The regression trend line of individual motor 0012199 (figure 21A) shows no significance.

For motor 0012199, five specimens failed 100% in the adhesive liner to propellant with one specimen failing 100% in the adhesive liner to case.

For motor STM-012, the failure mode for all specimens was 100% adhesive liner to propellant.

B. CREEP:

The composite regressions for the 10 and 12 pound load test show a statistically significant decreasing trend line slope (figures 22 thru 29).

C. STRESS RELAXATION:

The stress relaxation modulus composite regressions at 3% strain show a statistically significant positive trend at 10, 50 and 100 seconds with no significant trend direction at 1000 seconds (figures 30 thru 33). The 5% strain composite regressions at 10 and 50 seconds show a significant positive trend with no significant trend at 100 and 1000 seconds (figures 34 thru 37).

D. CONSTANT STRAIN:

The composite regression (figure 38) and the individual motor STM-012 (figure 38B) show a negative directed regression trend. The individual regression trend line for motor 0012199 (figure 38A) is not significant.

E. HARDNESS (Shore A):

The 10 second composite regression (figure 39) and individual motor STM-012 regression (figure 39C) have negative trend lines. Individual motors 0012099 (figure 39A) and 0012199 (figure 39B) are not significant.

F. DYNAMIC RESPONSE:

The composite regressions for loss tangent at 200 HZ (figure 40) and 400 HZ (figure 41) are not significant. The storage shear modulus composite regressions for 200 HZ (figure 42) and 400 HZ (figure 43) have significant decreasing trends in the negative direction.

G. SOL GEL:

The composite regression trend lines for % extractables and weight swell ratio have significant positive trends while density and crosslink density have negative trend line slopes (figures 44 thru 47).

H. BURNING RATE:

The 500 psi composite regression (figure 48) and the individual motor 0012099 regression (figure 48A) show a non-significant trend. The individual motor 0012199 (figure 48B) has a positive trend while motor STM-012 shows no change (figure 48C).

At 1000 psi, the composite regression (figure 49) and the individual motor 0012099 (figure 49A) have significant negative slope direction. The individual motor regression for motor 0012199 (figure 49B) is not significant. The individual regression for STM-012 (figure 49C) shows a significant negative trend line.

I. HEAT OF EXPLOSION:

The composite regression (figure 50) and individual regression for motor STM-012 (figure 50C) show significantly positive trend lines. The regressions for the individual motors 0012099 (figure 50A) and 0012199 (figure 50B) are not significant.

J. DIFFERENTIAL THERMAL ANALYSIS (DTA):

The endotherm composite regression (figure 51) and the individual regressions for motor 0012099 (figure 51A) and 0012199 (figure 51B) have significantly decreasing trend lines. Motor STM-012 is not significant (figure 51C).

The exotherm composite regression (figure 52) and individual motor 0012199 (figure 52B) are not significant. The individual motors 0012099

(figure 52A) and STM-012 (figure 52C) have significantly negative trends.

The ignition temperature composite regression (figure 53) and individual motor 0012199 (figure 53B) regression have non-significant trend lines. Individual motors 0012099 (figure 53A) and STM-012 (figure 53C) regressions have statistically significant positive trend line slopes.

SUMMARY, CONCLUSIONS AND RECOMMENDATIONS

A. TENSILE SUMMARY:

1. Combined Group Motors: Where significant changes are indicated, the changes are gradual and no problems are foreseen. The regression trends are not consistent when comparing the respective strains and stresses obtained under different conditions as seen in First Stage block testing. The most probable reason for this inconsistency is the variance between motors as shown in Table 2.

2. Individual Motors: For those regressions where significant trends are seen, the changes are gradual and no problems are indicated. These regressions show the same general trends as seen in the block propellant testing. The individual motor regressions show the propellant with less strain capability and higher tensile strength as the age increases.

B. THERMAL AND COMBUSTION SUMMARY:

From the analyses, the thermal properties are not undergoing a drastic change, with respect to age, at this time.

C. CONCLUSIONS:

The test results for both combined and individual motor regressions show that, under present storage conditions, some of the physical and combustion properties of the propellant indicate statistically significant aging trends. However, where a significant trend is indicated, the slope of the trend line is gradual and no operational problems are expected.

Although some aging trends have been observed, it does not appear that significant degradation will occur in the propellant within the next two years.

D. RECOMMENDATIONS:

It is recommended that motors be reported separately at the next test phase.

TABLE 2
 ANALYSIS OF COVARIANCE SUMMARY
 Comparison of Regressions Between 0012099, 0012199 & STM-012

Test	Residual			Difference Between		
	0012099	0012199	STM-012	Residual Trend Lines	Slope	Elevation
Tensile:						
Strain at Max Stress, 77°F, 2.0 in/min	.00029	.00023	.00016	S		
Strain at Rupture, 2.0 in/min, 77°F	.00046	.00045	.00042	NS	S	
Strain at Max Stress, 77°F, 20.0 in/min	.00027	.00046	.00070	S		
Strain at Rupture, 77°F, 20.0 in/min	.00047	.00100	.00048	S		
Case Bond, 77°F, 0.2 in/min		5.65	17.4	S		
Constant Strain, 77°F Strain at Rupture		4.81	7.30	NS	S	
Hardness, Shore A, 77°F, 10 sec	6.80	5.54	6.28	NS	NS	S
Burn Rate						
500 psi Initial Pressure	.00016	.00071	.00069	S		
1000 psi Initial Pressure	.00018	.00040	.00014	S		
Ignitability, Ignition Threshold Point 168						
	53.2	5.69	28.8	S		
Heat of Explosion						
	72.7	133.1	285.7	S		
DTA						
Endotherm 1	5.25	1.84	5.03	S		
Exotherm 1	4.14	4.49	14.16	S		
Ignition Temperature	169.5	114.4	38.5	S		

S = Data are significantly different
 NS = Data not significant

NOTE: Analysis performed at the 5% significant level

TABLE 3
REGRESSION TREND LINE SUMMARY

Test	Composite Three Motors	Individual Motors		
		0012099	0012199	STM-012
Low Rate Tensile, 77°F, 2.0 in/min				
Strain at Max Stress	NS	NS	-	NS
Maximum Stress	NS			
Strain at Rupture	NS	NS	-	-
Stress at Rupture	NS			
Modulus	NS			
Low Rate Tensile, 77°F, 20.0 in/min				
Strain at Max Stress	-	-	-	NS
Maximum Stress	NS	+	+	+
Strain at Rupture	-	-	-	NS
Stress at Rupture	NS			
Modulus	+			
High Rate Tensile, 77°F, 1750 in/in/min				
Strain at Max Stress	NS			
Maximum Stress	NS			
Strain at Rupture	-			
Stress at Rupture	NS			
Modulus	NS			
High Rate Triaxial Tensile, 1750 CHS, 600 psi, 77°F				
Strain at Max Stress	+			
Maximum Stress	NS			
Strain at Rupture	+			
Stress at Rupture	+			
Modulus	-			
Case Bond Tensile, 77°F			NS	-
Creep, 10 lb Load, 10 sec	-			
20 sec	-			
1000 sec	-			
10,000 sec	-			
Creep, 12 lb Load, 10 sec	-			
20 sec	-			
1000 sec	-			
10,000 sec	-			
Stress Relaxation, 3% Strain, 10 sec	+			
50 sec	+			
100 sec	+			
1000 sec	NS			
Stress Relaxation, 5% Strain, 10 sec	+			
50 sec	+			
100 sec	NS			
1000 sec	NS			

TABLE 3 (cont)

<u>Test</u>	<u>Composite Three Motors</u>	<u>Individual Motors</u>		
		<u>0012099</u>	<u>0012199</u>	<u>STM-012</u>
Constant Strain, 77° F	-		NS	-
Hardness, Shore A, 77° F, 10 sec	-	NS	NS	-
Dynamic Response				
Loss Tangent, 200 HZ	NS			
Loss Tangent, 400 HZ	NS			
Storage Shear Modulus, 200 HZ	-			
Storage Shear Modulus, 400 HZ	-			
Sol Gel				
% Extractables	+			
Weight Swell Ratio	+			
Density	-			
Crosslink Density	-			
Burning Rate				
500 psi	NS	NS	+	NS
1000 psi	-	-	NS	-
Heat of Explosion	+	NS	NS	+
DTA				
Endotherm 1	-	-	-	NS
Exotherm 1	NS	-	NS	-
Ignition Temperature	NS	+	NS	+

NS = Non-significant trend from a line of zero slope.

+ = Significant slope in a positive direction.

- = Significant slope in a negative direction.

$\gamma = ((+2.2311957E-01) + (-5.3563473E-06) \times X)$
 $F = +5.3470593E-02$ SIGNIFICANCE OF $F =$ NOT SIGNIFICANT $G_f = +2.0006216E-02$
 $R = -1.3917489E-02$ SIGNIFICANCE OF $R =$ NOT SIGNIFICANT $S_f = +2.3163875E-05$
 $\alpha = +2.3123709E-01$ SIGNIFICANCE OF $\alpha =$ NOT SIGNIFICANT $S_f = +2.0040485E-02$
 $N = 278$ DEGREES OF FREEDOM = 276 TEST CONDITIONS = HMB TEMP/RH
 STORAGE CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = IN/IN
 PARAMETER = STRAIN AT MAX STRESS
 0.00 4.00 8.00 12.00 16.00 20.00 24.00 28.00 32.00

- 15 -


STAGE 1 DISSECTED MOTORS, LOW RATE CHS=2.0 IN/MIN, STRAIN MAX STRESS

Figure 1

$F = +1.9475679E+00$ $Y = ((+2.2356723E-01) + (-5.6464484E-05) \times X)$
 $R = -1.6120092E-01$ $F = \text{NOT SIGNIFICANT}$ $\sigma_f = +1.7011705E-02$
 $t = +1.3955529E+00$ $F = \text{NOT SIGNIFICANT}$ $S_f = +4.0460296E-05$
 $N = 75$ $t = \text{NOT SIGNIFICANT}$ $S_t = +1.6903823E-02$
 $\text{DEGREES OF FREEDOM} = 73$ $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$

PARAMETER = STRAIN AT MAX STRESS

UNIT OF MEASURE = IN/IN



STAGE 1 DISSECTED MOTOR=0012099, LOW RATE CHS=2.0 IN/MIN, STRAIN MAX STRESS

Figure 1A

$F = +2.2389031E+01$ $F = (+2.7867189E-01)$ $F = (-2.1151371E-04)$ $X = X$
 $R = -4.6991808E-01$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = +4.7317048E+00$ SIGNIFICANCE OF R = SIGNIFICANT
 $N = 81$ DEGREES OF FREEDOM = 79
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH




Figure 1B

$F = +1.8424729E+00$ $\gamma = ((+2.0469608E-01) + (+3.9290561E-05) \times X)$
 $R = +1.2892806E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT $G_t = +1.2732718E-02$
 $t = +1.3573772E+00$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_o = +2.8945940E-05$
 $N = 111$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_t = +1.2684238E-02$
DEGREES OF FREEDOM = 109 TEST CONDITIONS = AMB TEMP/RH

STORAGE CONDITIONS = AMB TEMP/RH




Figure 1C

$F = +3.3240843E+00$ $\gamma = (+1.1824134E+02) + (+2.0056557E-02) \cdot \gamma$
 SIGNIFICANCE OF $F =$ NOT SIGNIFICANT $\sigma_c = +9.5572226E+00$
 $\alpha = +1.0908921E-01$ SIGNIFICANCE OF $\alpha =$ NOT SIGNIFICANT $S_c = +1.1000701E-02$
 $\lambda = +1.8232071E+00$ SIGNIFICANCE OF $\lambda =$ NOT SIGNIFICANT $S_r = +9.5173797E+00$
 $N = 278$ DEGREES OF FREEDOM = 276

TEST CONDITIONS = AMB TEMP/RH STORAGE CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = PSI
 PARAMETER = MAXIMUM STRESS

- 19 -




Figure 2

$\gamma = (+2.8325156E-01) + (-3.2674362E-06) \times X$
 $F = +1.4267133E-02$ SIGNIFICANCE OF $F = \text{NOT SIGNIFICANT}$ $\sigma_f = +2.3624446E-02$
 $R = -7.1895646E-03$ SIGNIFICANCE OF $R = \text{NOT SIGNIFICANT}$ $S_f = +2.7355128E-05$
 $t = +1.1944510E-01$ SIGNIFICANCE OF $t = \text{NOT SIGNIFICANT}$ $S_t = +2.3666594E-02$
 $N = 278$ DEGREES OF FREEDOM = 276
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG/F AMB-RH




Figure 3





Figure 3A

$F = +2.0032010E+01$ $\gamma = ((+3.4820935E-01) + (-2.8136210E-04) \times X)$
 $R = -4.4975348E-01$ SIGNIFICANCE OF F = SIGNIFICANT
 $A = +4.4757142E+00$ SIGNIFICANCE OF R = SIGNIFICANT
 $I = 81$ SIGNIFICANCE OF I = SIGNIFICANT
 $N = 79$ DEGREES OF FREEDOM = 79
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG/F AMB-RH

PARAMETER = STRAIN AT RUPTURE
 UNIT OF MEASURE = IN/IN
 0.20 0.24 0.28 0.32 0.36 0.40



STAGE 1 DISSECTED MOTOR=0012199, LOW RATE CHS=2.0 IN/MIN. STRAIN AT RUPTURE

Figure 3B




Figure 3C

$F = +8.3953098E-01$
 $F = +5.5068635E-02$
 $F = +9.1625923E-01$
 $N = 278$
 $Y = ((+1.0984765E+02) + (+1.0536261E-02) \ln X)$
 $F = \text{NOT SIGNIFICANT}$
 $F = \text{NOT SIGNIFICANT}$
 $F = \text{NOT SIGNIFICANT}$
 $F = \text{NOT SIGNIFICANT}$
 $Degrees of Freedom = 276$
 $Storage Conditions = \text{AMB TEMP/RH}$
 $Test Conditions = \text{AMB TEMP/RH}$

$Parameter = Stress at Rupture$
 $Unit of Measure = \text{PSI}$
 $0.00 \quad 100.00 \quad 120.00 \quad 140.00 \quad 160.00 \quad 180.00$





Figure 4

$\gamma = 11.1520746E+03$ + $(3.7051290E-01)$ $\times X$
 $F = 2.4884818E+00$ SIGNIFICANT $F =$ NOT SIGNIFICANT $\sigma_x = 1.9858738E+02$
 $F = 9.8885627E-02$ SIGNIFICANT $F =$ NOT SIGNIFICANT $\sigma_y = 2.3487462E-01$
 $F = 1.5774922E+00$ SIGNIFICANT $F =$ NOT SIGNIFICANT $\sigma_z = 1.9800576E+02$
 $i = 254$ DEGREES OF FREEDOM = 252
 $N =$ STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH



STAGE 1 DISSECTED MOTORS, LOW RATE CHS=2.0 IN/MIN. MODULUS

Figure 5





Figure 6

$F = 7.1186893E+00$ $F = 2.7924321E-01$ $F = 2.4710517E-04$
 $R = -3.7687746E-01$ SIGNIFICANCE OF F = SIGNIFICANT
 $L = +2.6680872E+00$ SIGNIFICANCE OF R = SIGNIFICANT
 $N = 45$ SIGNIFICANCE OF L = SIGNIFICANT
 DEGREES OF FREEDOM = 43 TEST CONDITIONS = AMB TEMP/RH
 STORAGE CONDITIONS = AMB TEMP/RH



STAGE I DISSECTED MOTOR-0012099, LOW RATE CHS=20.0 IN/MIN, STRAIN MH: STRESS

Figure 6A




Figure 6B

$\gamma = ((+2.4170107E-01) + (-7.8014971E-05) * X)$
 $F = +8.6441629E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT
 $R = -1.0817921E-01$ SIGNIFICANCE OF R = NOT SIGNIFICANT
 $\alpha = +9.2973990E-01$ SIGNIFICANCE OF α = NOT SIGNIFICANT
 $\beta = 75$ DEGREES OF FREEDOM = 73
 $N =$ STORAGE CONDITIONS = AMB TEMP/RH




Figure 6C

$F = +0.2956950E-02$ $Y = ((+1.5069226E+02) + (-8.2819333E-03) * X)$
 $R = -2.0674389E-02$ SIGNIFICANCE OF F = NOT SIGNIFICANT $G_f = +1.4738298E+01$
 $t = +2.8802248E-01$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_o = +2.8754468E-02$
 $N = 196$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_t = +1.4773076E+01$
DEGREES OF FREEDOM = 194 TEST CONDITIONS = AMB TEMP/RH

PARAMETER = MAXIMUM STRESS UNIT OF MEASURE = PSI
0.00 4.00 8.00 12.00 16.00 20.00 24.00 28.00 32.00

STAGE 1 DISSECTED MOTORS, LOW RATE CHS=20.0 IN/MIN, MAXIMUM STRESS




Figure 7




Figure 7A




Figure 7B




Figure 7C





Figure 8

$Y = ((+3.4309733E-01) + (-2.9298718E-04) * X) * X$
 $F = +5.6549660E+00$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -3.4091916E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $t = +2.3780172E+00$ SIGNIFICANCE OF t = SIGNIFICANT
 $N = 45$ DEGREES OF FREEDOM = 43
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

PARAMETER = STRAIN AT RUPTURE
 UNIT OF MEASURE = IN/IN
 0.20 0.24 0.28 0.32 0.36 0.40




STAGE 1 DISSECTED MOTOR=0012099, LOW RATE CHS=20.0 IN/MIN, STRAIN AT RUPTURE

Figure 8A

$F = +3.6096286E+01$ $Y = ((+4.1292679E-01) + (-5.6288191E-04) \times X)$
 $R = -5.6001622E-01$ $F = \text{SIGNIFICANT}$ $\sigma_r = +3.81110710E-02$
 $R = +6.0080185E+00$ $R = \text{SIGNIFICANT}$ $S_r = +9.3688444E-05$
 $N = 81$ $1 = \text{SIGNIFICANT}$ $S_r = +3.1773231E-02$
 $N = \text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$ $DEGREES OF FREEDOM = 79$ $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$

$\text{PARAMETER} = \text{STRAIN AT RUPUTURE}$
 $\text{UNIT OF MEASURE} = \text{IN/IN}$
 $0.00 \quad 0.24 \quad 0.32 \quad , \quad 0.40 \quad 0.48 \quad 0.56$



STAGE 1 DISSECTED MOTOR=0012199, LOW RATE CHS=20.0 IN/MIN, STRAIN AT RUPTURE

Figure 8B




Figure 8C






Figure 9



$F = +3.9193475E-01$ $\gamma = ((+1.8554433E-01) + (+4.4943198E-05) \times X)$
 $R = +4.8976932E-02$ SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_r = +4.8439564E-02$
 $L = +6.2604692E-01$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_o = +7.1788865E-05$
 $N = 165$ SIGNIFICANCE OF L = NOT SIGNIFICANT $S_t = +4.8529615E-02$
 D = DEGREES OF FREEDOM = 163 TEST CONDITIONS = AMB TEMP/RH

PARAMETER = STRAIN AT MAX STRESS

UNIT OF MEASURE = IN/IN



STAGE 1 DISSECTED MOTORS, HIGH RATE CHS=1750 IN/MIN. STRAIN MAX STRESS


Figure 11

$F = +3.6527524E+00$
 $R = -1.4804845E-01$
 $t = +1.9112175E+00$
 $N = 165$
 $\gamma = 11.4850835E+02$
 $\text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$
 $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$
 $\text{SIGNIFICANCE OF } F = \text{NOT SIGNIFICANT}$
 $\text{SIGNIFICANCE OF } R = \text{NOT SIGNIFICANT}$
 $\text{SIGNIFICANCE OF } t = \text{NOT SIGNIFICANT}$
 $\text{DEGREES OF FREEDOM} = 163$
 $\sigma_t = +3.9657615E+01$
 $S_t = +5.8195917E-02$
 $S_e = +3.9340717E+01$

UNIT OF MEASURE = PSI

PARAMETER = MAXIMUM STRESS

- 41 -



STAGE 1 DISSECTED MOTORS, HIGH RATE CHS=1750 IN/MIN, MAXIMUM STRESS

Figure 12





Figure 13

$\gamma = ((+2.9541027E+02) + (-2.9999835E-02) * X) * X$
 $F = +2.5121679E-01$
 $F = \text{SIGNIFICANCE OF } F = \text{NOT SIGNIFICANT}$
 $R = -3.9227995E-02$
 $R = \text{SIGNIFICANCE OF } R = \text{NOT SIGNIFICANT}$
 $\alpha = +5.0121531E-01$
 $\alpha = \text{SIGNIFICANCE OF } \alpha = \text{NOT SIGNIFICANT}$
 $N = 165$
 $\text{DEGREES OF FREEDOM} = 163$
 $\text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$ TEST CONDITIONS = AMB TEMP/RH

PARAMETER = STRESS AT RUPTURE
 UNIT OF MEASURE = PSI
 0.00 400.00 320.00 400.00 480.00 560.00



STAGE 1 DISSECTED MOTORS, HIGH RATE CHS=1750 IN/MIN, STRESS AT RUPTURE

Figure 14

$F = +2.6779774E+00$ $\gamma = ((+7.1613748E+03) + (-4.4295912E+00) \times X)$
 $R = -1.2713673E-01$ $F = \text{NOT SIGNIFICANT}$ $G_r = +1.8391638E+03$
 $L = +1.6364526E+00$ $R = \text{NOT SIGNIFICANT}$ $S_o = +2.7068251E+00$
 $N = 165$ $L = \text{NOT SIGNIFICANT}$ $S_r = +1.82988267E+03$
 $\text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$ $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$
 $\text{DEGREES OF FREEDOM} = 163$

$\text{PARAMETER} = \text{MODULUS}$
 $\text{UNIT OF MEASURE} = \text{PSI}$
 $0.00 \quad 40.00 \quad 80.00 \quad 120.00 \quad 160.00 \quad 200.00 \quad 10^2$




Figure 15

$F = +1.0563994E+02$
 $R = +7.5845620E-01$
 $t = +1.0278129E+01$
 $N = 80$

$Y = ((+1.3815354E-01) + (+6.1840822E-04) * X)$
 $F = \text{SIGNIFICANT}$
 $R = \text{SIGNIFICANT}$
 $t = \text{SIGNIFICANT}$
 $N = \text{DEGREES OF FREEDOM} = 78$

$\text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$
 $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$

PARAMETER = STRAIN AT MAX STRESS UNIT OF MEASURE = IN/IN





Figure 16

$\gamma = (+5.7276589E+02) + (+1.7267874E-01) \times X$
 $F = \text{SIGNIFICANCE OF } \gamma = \text{NOT SIGNIFICANT}$
 $R = \text{SIGNIFICANCE OF } \alpha = \text{NOT SIGNIFICANT}$
 $\alpha = \text{SIGNIFICANCE OF } \beta = \text{NOT SIGNIFICANT}$
 $\beta = \text{DEGREES OF FREEDOM} = 78$
 $N = 80$
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = PSI
 PARAMETER = MAXIMUM STRESS




DISSECTED TIP-H1011, H.R. TRIAXIAL CHS=1750 IN/MIN, 600 PSI, MAXIMUM STRESS

Figure 17

$F = +7.2480134E+01$ $R = (+1.9615422E-01)$ $F = (+5.3631395E-04)$ $X = (\sigma_r = +4.1362948E-02)$
 $R = +6.9401668E-01$ $R = \text{SIGNIFICANT}$ $S_0 = +6.2995511E-05$
 $I = +8.5135265E+00$ $I = \text{SIGNIFICANT}$ $S_t = +2.9969910E-02$
 $N = 80$ $\text{DEGREES OF FREEDOM} = 78$ $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$

PARAMETER = STRAIN AT RUPTURE $\text{UNIT OF MEASURE} = \text{IN/IN}$
 0.00 4.00 8.00 12.00 16.00 20.00 24.00 28.00 32.00



DISSECTED TP-H1011.H.R. TRIAXIAL CHS=1750 IN/MIN, 600 PSI, STRAIN AT RUPTURE

Figure 18




Figure 19




Figure 20




Figure 21

$F = +2.7852661E-01$ $Y = ((+1.0358290E+02) + (-3.4546892E-02) * X)$
 $R = -5.4644003E-02$ SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_r = +2.3683940E+01$
 $A = +5.2775620E-01$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_o = +6.5459946E-02$
 $I = 95$ SIGNIFICANCE OF I = NOT SIGNIFICANT $S_r = +2.3775357E+01$
 $N = 93$ DEGREES OF FREEDOM = 93 TEST CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = PSI MAXIMUM STRESS = 200.00
 0.00 40.00 80.00 120.00 160.00 200.00

PARAMETER = MAXIMUM STRESS

- 51 -




Figure 21A




Figure 21B

$Y = (+1.5458807E-03) + (-2.6282996E-06) * X$
 $F = +1.3104752E+01$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -4.4865040E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $R^2 = +3.6200486E+00$ SIGNIFICANCE OF R^2 = SIGNIFICANT
 $N = 54$ DEGREES OF FREEDOM = 52
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

PARAMETER = COMPLIANCE
 UNIT OF MEASURE = INCHIN/LBS $\times 10^{-2}$
 0.02 0.06 0.10 0.14 0.18 0.22
 0.00 4.00 8.00 12.00 16.00 20.00 24.00 28.00 32.00





Figure 22


$\gamma = ((+1.8144300E+01 + 1.3853340E-06) * X) + 1.0144300E-03$
 $F = \text{SIGNIFICANCE OF } F = \text{SIGNIFICANT}$
 $R = \text{SIGNIFICANCE OF } R = \text{SIGNIFICANT}$
 $I = \text{SIGNIFICANCE OF } I = \text{SIGNIFICANT}$
 $N = 54$
 $\text{DEGREES OF FREEDOM} = 52$
 $\text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$
 $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$



DISSECTED MOTOR TP-H1011. CREEP 12 LB LOAD, COMPLIANCE AT 20 SEC.

Figure 23

$Y = 11 + 2.9776665E-03 F + (-5.2010823E-06) F^2 \times X$
 $F = \text{SIGNIFICANCE OF } F$
 $F = \text{SIGNIFICANCE OF } R$
 $R = \text{SIGNIFICANCE OF } t$
 $t = \text{DEGREES OF FREEDOM} = 52$
 $N = \text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$ TEST CONDITIONS = AMB TEMP/RH







Figure 25

$F = +1.2213572E+01$ $Y = ((+1.3218815E-03) + (-2.2678021E-06) \times X)$
 $R = -4.2627794E-01$ $F = \text{SIGNIFICANT}$
 $R = +3.4947921E+00$ $R = \text{SIGNIFICANT}$
 $N = 57$ $N = \text{DEGREES OF FREEDOM} = 55$
 $\text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$ $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$



DISSECTED MOTOR TP-H1011, CREEP 10 LB LOAD, COMPLIANCE AT 10 SEC.

Figure 26





Figure 27

$F = +8.7628573E+00$ $\gamma = ((+2.2455179E-03) + (-3.3703536E-06) \times X)$
 $R = -3.7071399E-01$ SIGNIFICANCE OF $F = \text{SIGNIFICANT}$
 $I = +2.9602123E+00$ SIGNIFICANCE OF $R = \text{SIGNIFICANT}$
 $N = 57$ SIGNIFICANCE OF $I = \text{SIGNIFICANT}$
 $\text{DEGREES OF FREEDOM} = 55$ TEST CONDITIONS = AMB TEMP/RH

PARAMETER = COMPLIANCE
 $\text{LIMIT OF MEASURE} = 0.16 \text{ INCHIN/LBS}$
 $\times 10^{-2}$
 0.00 0.08 0.16 0.24 0.32 0.40



DISSECTED MOTOR TP-H1011, CREEP 10 LB LOAD, COMPLIANCE AT 1000 SEC.

Figure 28





Figure 29

$F = +7.9078507E+00$ $\gamma = (1.2783296E+02) + (1.9016711E-01) \times X$
 $R = +2.6823464E-01$ SIGNIFICANT
 $\alpha = +2.8120901E+00$ SIGNIFICANT
 $N = 104$ SIGNIFICANT
 $N = 102$ DEGREES OF FREEDOM
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH



TP-H1011 DISSECTED MIRS, STRESS RELAXATION MODULUS, 3 PERCENT STRAIN, 10 SEC

Figure 30




Figure 31

$F = +5.0895305E+00$ $\gamma = ((+4.6019416E+02) + (+4.2568314E-01) \times X)$
 $R = +2.1800444E-01$ SIGNIFICANCE OF F = SIGNIFICANT
 $\epsilon = +2.2559987E+00$ SIGNIFICANCE OF R = SIGNIFICANT
 $N = 104$ SIGNIFICANCE OF ϵ = SIGNIFICANT
 DEGREES OF FREEDOM = 102
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

UNITS OF MEASURE = PSI $\times 10^3$
 PARAMETER = STRESS RELAX MODULUS

- 63 -

TP-H1011 DISSECTED MIRS, STRESS RELAXATION MODULUS, 3 PERCENT STRAIN, 100 SEC

Figure 32

$\gamma = ((+3.7669280E+02) + (+2.5778664E-01) \times X)$
 $F = +2.3360925E+00$ SIGNIFICANCE OF F = NOT SIGNIFICANT
 $R = +1.5183187E-01$ SIGNIFICANCE OF R = NOT SIGNIFICANT
 $A = +1.5284281E+00$ SIGNIFICANCE OF A = NOT SIGNIFICANT
 $\alpha = 101$ DEGREES OF FREEDOM = 99
 $N = 101$ STORAGE CONDITIONS = AMB TEMP/RH


PARAMETER = STRESS RELAX MODULUS

UNIT OF MEASURE = PSI $\times 10^4$

TP-H1011 DISSECTED MTRs. STRESS RELAXATION MODULUS. 3 PERCENT STRAIN, 1000 SEC

Figure 33

$\gamma = ((+6.6894988E+02) + (+7.0640952E-01) \times X)$
 $F = +7.6999031E+00$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = +2.6255254E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $\alpha = +2.77486699E+00$ SIGNIFICANCE OF α = SIGNIFICANT
 $N = 106$ DEGREES OF FREEDOM = 104
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH




TP-H1011 DISSECTED MTRs, STRESS RELAXATION MODULUS, 5 PERCENT STRAIN, 10 SEC

Figure 34

$\gamma = ((+5.0238097E+02) + (+3.7121134E-01) \times X)$
 $F = +4.7423191E+00$ SIGNIFICANCE OF F = SIGNIFICANT
 $\alpha = +2.0883154E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $\beta = +2.1776866E+00$ SIGNIFICANCE OF L = SIGNIFICANT
 $N = 106$ DEGREES OF FREEDOM = 104
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

UNITS OF MEASURE = PSI
 PARAMETER = STRESS RELAX MODULUS
 0.00 40.00 60.00 80.00 100.00 $\times 10^3$ 120.00



TP-H1011 DISSECTED MTRS. STRESS RELAXATION MODULUS, 5 PERCENT STRAIN, 50 SEC

Figure 35

$F = +3.7654645E+00$ $Y = ((+4.7039791E+02) + (+3.0465259E-01) \times X)$
 $F = +1.8692589E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_t = +8.6743359E+01$
 $F = +1.9404804E+00$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_0 = +1.5699853E-01$
 $N = 106$ DEGREES OF FREEDOM = 104 SIGNIFICANCE OF $t =$ NOT SIGNIFICANT $S_t = +8.5623127E+01$
 $S =$ STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

INIT OF MEASURE = PSI $40.00 \quad 60.00 \quad 80.00 \quad 100.00 \quad 120.00$
 $\times 10^3$
 PARAMETER = STRESS RELAX MODULUS





Figure 36

STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

PARAMETER = STRESS RELAX MODULUS

UNIT OF MEASURE = PSI 10.00 28.00 38.00 48.00 58.00 68.00



TP-H1011 DISSECTED MIRS, STRESS RELAXATION MODULUS. 5 PERCENT STRAIN. 1000 SEC

Figure 37

F = +3.6315618E+01 Y = 1 (+2.6260195E+01) + (-5.3831497E-02) * X₁
 R = -6.8982671E-01 F = SIGNIFICANT
 I = +6.0262441E+00 R = SIGNIFICANT
 N = 42 DEGREES OF FREEDOM = 40
 STORAGE CONDITIONS = AMBIENT TEMP/RH TEST CONDITIONS = AMBIENT TEMP/RH

PARAMETER = STRAIN AT RUPTURE
UNIT OF MEASURE = PERCENT
P. 00 8.00 16.00 , 24.00 32.00 40.00

PARAMETER = STRAIN AT RUPTURE

STAGE 1 OSSCTD MTRAS, CONSTANT STRAIN, STRAIN 0.1 INIT AND 0.01 EVERY 48 HRS

Figure 38

$F = +3.3168119E+00$ $\gamma = ((+2.1375756E+01) + (-2.5135436E-02)) * X$
 $R = -5.6700601E-01$ SIGNIFICANCE OF $F = \text{NOT SIGNIFICANT}$ $G_r = +2.0275875E+00$
 $I = +1.8212116E+00$ SIGNIFICANCE OF $R = \text{NOT SIGNIFICANT}$ $S_b = +1.380491E-02$
 $N = 9$ SIGNIFICANCE OF $I = \text{NOT SIGNIFICANT}$ $S_t = +1.7854670E+00$
 $\text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$ $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$

$\text{PARAMETER} = \text{STRAIN AT RUTURE}$
 $\text{UNIT OF MEASURE} = \text{PERCENT}$
 $0.00 \quad 4.00 \quad 8.00 \quad 12.00 \quad 16.00 \quad 20.00 \quad 24.00 \quad 28.00 \quad 32.00$

STAGE 1, DSSCTD MTR=0012199, CONSTANT STRAIN, STRAIN 0.1 INIT & 0.01 EVERY 48 HRS.

Figure 38A




Figure 38B




Figure 39





Figure 39A

$\gamma = 11 \left(+6.6405700E+01 \right) + \left(+6.1895352E-03 \right) * X$
 $F = +6.8624941E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_f = +2.3494828E+00$
 $R = +7.8386475E-02$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_r = +7.4716591E-03$
 $t = +8.2840172E-01$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_t = +2.3527806E+00$
 $N = 113$ DEGREES OF FREEDOM = 111 TEST CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = SHORE A
 PARAMETER = 10 SECOND HARDNESS
 80.00 76.00 72.00 68.00 64.00 4.00 0.00




STAGE 1. DISSECTED MOTOR=110012199, SHORE-A HARDNESS, 10 SECOND.

Figure 398

$F = +4.8091481E+00$ $\gamma = 1(+6.8105243E+01) + (-1.3852707E-02) \times X_1$
 $R = -1.9869828E-01$ $F = \text{SIGNIFICANT}$ $G_f = +2.5217910E+00$
 $\lambda = +2.1929770E+00$ $R = \text{SIGNIFICANT}$ $S_0 = +6.3168504E-03$
 $N = 119$ $\lambda = \text{SIGNIFICANT}$ $S_\epsilon = +2.4820478E+00$
 DEGREES OF FREEDOM = 117 TEST CONDITIONS = AMB TEMP/RH

STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = SHORE A PARAMETER = 10 SECOND HARDNESS




STAGE 1, DISSECTED MOTOR=(S) STM-012, SHORE-A HARDNESS, 10 SECOND.

Figure 39C

$F = +1.5183324E+00$ $\gamma = 11 +5.6207916E-01$ $\beta = (+2.4108331E-04) \times X$
 $R = +1.9357873E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_i = +4.3338176E-02$
 $I = +1.2322063E+00$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_o = +1.9565174E-04$
 $N = 41$ SIGNIFICANCE OF I = NOT SIGNIFICANT $S_i = +4.3060081E-02$
 DEGREES OF FREEDOM = 39 TEST CONDITIONS = AMB TEMP/RH

PARAMETER = LOSS TANG 200 Hz
 UNIT OF MEASURE = PSI
 0.40 0.48 0.56 0.64 0.72 0.80



STAGE I DISSECTED MOTORS, DYNAMIC RESPONSE, CENTER-WT 70 GM, LOSS TANG AT 200 Hz

Figure 40





Figure 41

$F = 4.9658665E+00$ $Y = ((4.8408579E+03) + 1 - 7.1612581E+00) * X)$
 $F =$ SIGNIFICANCE OF F = SIGNIFICANT $G = +7.4149932E+02$
 $R = -3.3607770E-01$ SIGNIFICANCE OF R = SIGNIFICANT $S_1 = +3.2135999E+00$
 $1 = +2.2284224E+00$ SIGNIFICANCE OF 1 = SIGNIFICANT $S_2 = +7.0726625E+02$
 $N = 39$ DEGREES OF FREEDOM = 39 TEST CONDITIONS = AMB TEMP/RH

PARAMETER = STOR SHEAR 200 Hz
 UNIT OF MEASURE = PSI
 0.00 20.00 40.00 60.00 80.00 $\times 10^2$ 100.00



STAGE I DISSECTED MOTORS, DYNAMIC RESPONSE, CENTER-WI 70 GM, STOR SHEAR AT 200 Hz

Figure 42




Figure 43

$F = +8.1989779E+00$ $\gamma = ((+6.3969915E+00) + (+4.1690238E-03) \times X)$
 $F = \text{SIGNIFICANCE OF } F$ $\gamma = \text{SIGNIFICANT}$
 $R = +3.1582510E-01$ $F = \text{SIGNIFICANT}$
 $\alpha = +2.06633857E+00$ $R = \text{SIGNIFICANT}$
 $N = 76$ $\alpha = \text{SIGNIFICANT}$
 $\text{DEGREES OF FREEDOM} = 74$
 $\text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$ $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$




Figure 44




Figure 45

$F = +1.4213338E+01$ $F = +1.7899702E+00$ $F = -1.1621495E-04$ $F = X$
 $R = -4.0140327E-01$ $R = +3.0825773E-05$
 $I = +3.7700581E+00$ $I = +8.1016647E-03$
 $N = 76$ $Degrees of Freedom = 74$ $Storage Conditions = Amb Temp/RH$ $Test Conditions = Amb Temp/RH$

$Parameter = Density$
 $Unit of Measure = Grams/CC$
 $1.72, 1.74, 1.76, 1.78, 1.80$





Figure 46

$\gamma = (+1.4295726E-02) + (-1.9675902E-05) * X$
 $F = +1.1336245E+01$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -3.6447509E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $I = +3.3669341E+00$ SIGNIFICANCE OF I = SIGNIFICANT
 $N = 76$ DEGREES OF FREEDOM = 74
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

PARAMETER = CROSSTALK DENSITY
 UNIT OF MEASURE = MILLIEGKV/CC $\times 10^{-1}$
 0.04 0.08 0.12 0.16 0.20 0.24



DISSECTED MTR, STAGE 1, TP-H1011, SOL GEL, CROSSTALK DENSITY

Figure 47

$F = +4.7992488E-03$ $\gamma = ((+2.5697084E-01) + (+2.9816754E-06)) * X$
 $F = \text{SIGNIFICANT}$
 $F = \text{NOT SIGNIFICANT}$
 $F = +6.0526147E-03$ $\sigma_f = +2.4140148E-02$
 $F = \text{SIGNIFICANT}$
 $F = \text{NOT SIGNIFICANT}$
 $F = +6.9276611E-02$ $S_0 = +4.3040145E-05$
 $F = \text{SIGNIFICANT}$
 $F = \text{NOT SIGNIFICANT}$
 $N = 133$ $S_1 = +2.4231667E-02$
 $\text{DEGREES OF FREEDOM} = 131$
 $\text{TEST CONDITIONS} = \text{AMB TEMP/RH}$
 $\text{STORAGE CONDITIONS} = \text{AMB TEMP/RH}$

PARAMETER = BURNING RATE
 UNIT OF MEASURE = IN/SEC
 0.16 0.20 0.24 0.28 0.32 0.36




Figure 48





Figure 48A

AD-A139 201 SURVEILLANCE REPORT STAGE I DISSECTED MOTORS PHASE XIV
PROPELLANT AND COM. (U) OGDEN AIR LOGISTICS CENTER HILL
AFB UT PROPELLANT ANALYSIS LA.. J A THOMPSON DEC 83
UNCLASSIFIED MANPA-482(83) 22
F/G 21/9.2 NL


END
DATE PRINTED
4-22-84
DTIC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

$F = +1.0044371E+01$ $\gamma = 1(+2.0210558E-01) + (+3.3768864E-04) \times X$
 $R = +4.4359581E-01$ SIGNIFICANCE OF $F = \text{SIGNIFICANT}$ $\sigma_F = +2.92555610E-02$
 $R = +3.1692655E+00$ SIGNIFICANCE OF $R = \text{SIGNIFICANT}$ $S_R = +1.0654408E-04$
 $\nu_1 = +3.1692655E+00$ SIGNIFICANCE OF $\nu_1 = \text{SIGNIFICANT}$ $S_{\nu_1} = +2.6537492E-02$
 $N = 43$ DEGREES OF FREEDOM = 41
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = INCHES/SEC
 PARAMETER = BURNING RATE




STAGE 1 DISSECTED MOTOR = (1)0012199. BURNING RATE AT 500 PSI INITIAL PRESSURE.

Figure 48B

$F = +2.5212784E+00$ $Y = ((+2.7678951E-01) + (-1.1447645E-04) * X)$
 $R = -2.2339489E-01$ $F = \text{NOT SIGNIFICANT}$ $S_f = +2.6600233E-02$
 $I = +1.5878534E+00$ $A = \text{NOT SIGNIFICANT}$ $S_a = +7.2095104E-05$
 $N = 50$ $L = \text{NOT SIGNIFICANT}$ $S_L = +2.61966684E-02$
 $\text{DEGREES OF FREEDOM} = 48$

TEST CONDITIONS = AMB TEMP/RH
 STORAGE CONDITIONS = AMB TEMP/RH

$\text{PARAMETER} = \text{BURNING RATE}$
 $\text{UNIT OF MEASURE} = \text{INCHES/SEC}$
 $0.00 \quad 0.20 \quad 0.24 \quad , \quad 0.28 \quad 0.32 \quad 0.36$



STAGE 1, DISSECTED MOTOR = (S1) STM-012, BURNING RATE AT 500 PSI INITIAL PRESSURE.

Figure 48C

$F = +6.7610346E+01$ $\gamma = ((+3.4079777E-01) + (-2.4127323E-04) \times X)$
 $R = -5.3455170E-01$ SIGNIFICANT
 $I = +8.2225511E+00$ SIGNIFICANT
 $N = 171$ SIGNIFICANT
 $Degrees of Freedom = 169$ TEST CONDITIONS = AMB TEMP/RH

STORAGE CONDITIONS = AMB TEMP/RH




Figure 49





Figure 49A

$\gamma = (1.0140412E-01) + (-1.0529740E-05) \times \chi$
 $F = +1.9554861E-02$ SIGNIFICANCE OF F = NOT SIGNIFICANT
 $R = -1.9026191E-02$ SIGNIFICANCE OF R = NOT SIGNIFICANT
 $L = +1.3983869E-01$ SIGNIFICANCE OF L = NOT SIGNIFICANT
 $N = 56$ DEGREES OF FREEDOM = 54

STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

PARAMETER = BURNING RATE
 UNIT OF MEASURE = INCHES/SEC
 0.20 0.24 0.28 0.32 0.36 0.40




STAGE 1. DISSECTED MOTOR= (1) 0012199. BURNING RATE AT 1000 PSI INITIAL PRESSURE.

Figure 49B

$F = +1.8574907E+02$ SIGNIFICANCE OF $F =$ SIGNIFICANT
 $R = -8.5122796E-01$ SIGNIFICANCE OF $R =$ SIGNIFICANT
 $I = +1.2874357E+01$ SIGNIFICANCE OF $I =$ SIGNIFICANT
 $N = 65$ DEGREES OF FREEDOM = 63

STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

PARAMETER = BURNING RATE
 UNIT OF MEASURE = INCHES/SEC
 0.20 0.24 0.28 0.32 0.36 0.40



STAGE 1, DISSECTED MOTOR: (S) STM-012, BURNING RATE AT 1000 PSI INITIAL PRESSURE.

Figure 49C


$F = +1.5910074E+01$ $F = (+1.5245202E+03) + (+1.5460811E-01) * X_1$
 $F = +4.5189682E-01$ $F = \text{SIGNIFICANT}$
 $F = +3.9887434E+00$ $F = \text{SIGNIFICANT}$
 $N = 64$ $R = \text{SIGNIFICANT}$
 $N = 64$ $R = \text{SIGNIFICANT}$
 $N = 64$ $R = \text{SIGNIFICANT}$
 $N = 64$ $D = \text{DEGREES OF FREEDOM} = 62$
 $N = 64$ $TEST CONDITIONS = \text{AMB TEMP/RH}$


UNIT OF MEASURE = CRL/GRAM

PARMETER = HEAT OF EXPLOSION

STAGE I DISSECTED MOTORS. HEAT OF EXPLOSION

Figure 50






STAGE 1, DISSECTED MOTOR=0012099, HEAT RELEASED AT IGNITION.

Figure 50A

$F = +9.167333E-03$ $\gamma = ((+1.5450797E+03) + (-8.7754528E-03) * X) * X$
 $R = -2.4714009E-02$ $\sigma_f = +1.0270864E+01$
 $I = +9.5746192E-02$ $S_a = +9.1653282E-02$
 $N = 17$ $S_r = +1.0604463E+01$
 $Degrees of Freedom = 15$
 $Storage Conditions = A M B \text{ TEMP / RH}$

$Parameter = Heat of Explosion$
 $Unit of Measure = CAL/GRAM$
 $0.00 \quad 1520.00 \quad 1540.00 \quad 1560.00 \quad 1580.00 \quad 1600.00$




STAGE 1. DISSECTED MOTOR=0012199. HEAT RELEASED AT IGNITION.

Figure 50B

$Y = ((+1.5095914E+03) + (+2.5571090E-01) * X)$
 $F = +1.5124228E+01$ SIGNIFICANT
 $R = +6.0643985E-01$ SIGNIFICANT
 $\alpha = +3.8889881E+00$ SIGNIFICANT
 $N = 28$ DEGREES OF FREEDOM = 26

STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = CAL/GRAM
 PARAMETER = HEAT OF EXPLOSION
 480.00 1520.00 1560.00 1600.00 1640.00 1680.00




STAGE 1, DISSECTED MOTOR=STM-012, HEAT RELEASED AT IGNITION.

Figure 50C

$Y = ((+2.4538636E+02) + (-2.7156570E-02) \times X)$
 $F = +1.0315407E+01$ SIGNIFICANT
 $R = -3.9439915E-01$ SIGNIFICANT
 $R = +3.2117608E+00$ SIGNIFICANT
 $I = 58$ DEGREES OF FREEDOM = 56
 $N = 58$ STORAGE CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = DEGREES C
 PARAMETER = ENDOOTHERM 1
 232.00 236.00 240.00 244.00 248.00 252.00
 0.00 4.00 8.00 12.00 16.00 20.00 24.00 28.00 32.00




STAGE 1. DSC TD MTRS= (0) 0012099, (1) 0012199, (S) STM-012.DTA, 12 DEG C RISE/MIN.

Figure 51

$F = +1.3004793E+01$
 $R = -6.4764542E-01$
 $I = +3.6062158E+00$
 $N = 20$
 $Y = ((+2.4824775E+02) + (-4.9945568E-02) * X) +$
 F = SIGNIFICANCE OF F = SIGNIFICANT
 R = SIGNIFICANCE OF R = SIGNIFICANT
 I = SIGNIFICANCE OF I = SIGNIFICANT
 N = DEGREES OF FREEDOM = 18
 $STORAGE CONDITIONS = AMB TEMP/RH$

$UNIT OF MEASURE = DEGREES C$
 $PARAMETER = ENDOTHERM 1$




STAGE 1, DISSECTED MTR = (0) 0012099, DTA, ENDOTHERM 1, 12 DEG C RISE/MIN.

Figure 51A

$F = +2.6246928E+01$ $Y = ((+2.5222610E+02) + (-7.4974458E-02) * X)$
 $F =$ SIGNIFICANCE OF F = $\sigma_F = +2.2740775E+00$
 $F =$ SIGNIFICANCE OF F = $S_F = +1.4634372E-02$
 $F =$ SIGNIFICANCE OF F = $S_F = +1.3582085E+00$
 $F =$ SIGNIFICANT DEGREES OF FREEDOM = 13
 $N = 15$ $STORAGE CONDITIONS = AMB TEMP/RH$ $TEST CONDITIONS = AMB TEMP/RH$

UNIT OF MEASURE = DEGREES C
 PARAMETER = ENDOTHERM 1
 232.00 236.00 240.00 244.00 248.00 252.00



STAGE 1.0 DISSECTED MTR = (1) 0012199.0TA, ENDOTHERM 1, 12 DEG C RISE/MIN.

Figure 51B

$F = +4.0117108E-02$ $Y = (+2.4141923E+02) + (-2.4394493E-03) \times X$
 $F =$ SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_F = +2.1941351E+00$
 $R = +4.3665731E-02$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_0 = +1.2179430E-02$
 $R^2 = +2.0029255E-01$ SIGNIFICANCE OF R^2 = NOT SIGNIFICANT $S_r = +2.2436269E+00$
 $N = 23$ DEGREES OF FREEDOM = 21
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = DEGREES C
 232.00 236.00 240.00 244.00 248.00 252.00
 PARAMETER = ENDOOTHERM 1


STAGE 1. DISSECTED MTR-(S) STH-012, DIA. ENDOOTHERM 1, 12 DEG C RISE/MIN.

Figure 51C

STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH


PARARMETER = EXOTHERM 1
UNIT OF MERSURE = DEGREES C
2.00 280.00 288.00, 296.00 304.00 312.00

PARAMETER = EXOTHERM 1



STATE 1,0510 M1HS=10) 0012099, (1) 0012199, (9) S1M-01S.01A.12 DEG C A1SE/MIN.

Figure 52




STAGE 1. DISSECTED MTR = (0) 0012099.01A. EXOTHERM 1. 12 DEG C RISE/MIN.

Figure 52A

$F = +4.37854996E-01$ $y = ((+2.9050362E+02) + (-1.5115631E-02) * x)$
 $R = -1.8050954E-01$ $F = \text{NOT SIGNIFICANT}$ $S_f = +2.0770858E+00$
 $N = +6.6170610E-01$ $F = \text{NOT SIGNIFICANT}$ $S_g = +2.2843421E-02$
 $N = 15$ $R = \text{NOT SIGNIFICANT}$ $S_h = +2.1200860E+00$
 $N = 13$ $DGREES OF FREEDOM = 13$ TEST CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = DEGREES C
 PARAMETER = EXOTHERM 1




STAGE 1, DISSECTED MTR = (1) 0012199, DTA, EXOTHERM 1, 12 DEG C RISE/MIN.

Figure 52B

$F = +7.175118E+00$ $\gamma = ((+3.0410796E+02) + (-5.4723614E-02) \times X)$
 $R = -5.0470271E-01$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = +2.6790878E+00$ SIGNIFICANCE OF R = SIGNIFICANT
 $N = 23$ DEGREES OF FREEDOM = 21
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = DEGREES C
 PARAMETER = EXOTHERM 1
 280.00 288.00 296.00 304.00 312.00 320.00



STAGE 1, DISSECTED MTR = (S1) STH-012, DTA, EXOTHERM 1, 12 DEG C RISE/MIN.

Figure 52C

$\gamma = ((+3.5707581E+02) + (+9.0211672E-02) \times x)$
 $F = +3.6489148E+00$ SIGNIFICANCE OF $F =$ NOT SIGNIFICANT
 $F_t = +1.2453692E+01$
 $R = +2.9961074E-01$ SIGNIFICANCE OF $R =$ NOT SIGNIFICANT
 $S_a = +4.7225968E-02$
 $t = +1.9102133E+00$ SIGNIFICANCE OF $t =$ NOT SIGNIFICANT
 $S_e = +1.2041080E+01$
 $N = 39$ DEGREES OF FREEDOM = 37
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH

UNIT OF MEASURE = DEGREES C
 PARAMETER = IGNITION TEMP
 0.00 320.00 340.00 360.00 380.00 400.00 420.00

- 104 -




Figure 53

$y = ((+3.5247055E+02) + (+2.3485545E-01) \times x)$
 $F = +6.2894886E+00$ $F =$ SIGNIFICANT
 $R = +6.8794470E-01$ $R =$ SIGNIFICANT
 $S = +2.5078852E+00$ $S =$ SIGNIFICANT
 $N = 9$ $N =$ DEGREES OF FREEDOM = 7
 $STORAGE CONDITIONS = AMB TEMP/RH$

$PARAMETER = IGNITION TEMP$
 $UNIT OF MEASURE = DEGREES C$
 $0.00 \quad 320.00 \quad 350.00 \quad 380.00 \quad 400.00 \quad 440.00 \quad 480.00 \quad 520.00$

- 105 -




STAGE 1. DISSECTED MTR = (0) 0012099. DTA. IGNITION TEMP. 12 DEG C RISE/MIN.

Figure 53A

$F = +1.9807403E+00$ $y = ((+3.4092850E+02) + (+1.09976277E-01) * x)$
 $R = +4.2471535E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT $G_f = +1.1207951E+01$
 $I = +1.4073877E+00$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_f = +1.3483333E-01$
 $N = 11$ SIGNIFICANCE OF I = NOT SIGNIFICANT $S_I = +1.0695730E+01$
DEGREES OF FREEDOM = 9 TEST CONDITIONS = AMB TEMP/RH

STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH
UNIT OF MEASURE = DEGREES C
320.00 340.00 360.00 380.00 400.00 420.00

PARAMETER = IGNITION TEMP



STAGE 1. DISSECTED MTR- (1) 0012199.01A, IGNITION TEMP, 12 DEG C RISE/MIN.

Figure 53B




Figure 53C .

DISTRIBUTION

NR
COPIES

OOALC	
MMWRBM	1
MMWRAM	1
DDC (TISIR) Cameron Station, Alexandria, VA 22314	2
SAMSO, Norton AFB, CA 92409	1
Attn: Mr. Sanford Collins, Bldg. 562, Room 613	
AFPRO, Thiokol Chemical Corporation	2
Wasatch Division	
P.O. Box 524	
Brigham City, UT 84302	
(Cy to Larry Hales)	
AFRPL (MKPB) Edwards AFB, CA 93523	1
SAC (LGBM) Offutt AFB, NB 68113	1
U. S. Naval Ordnance Station, Indian Head, MD 20460	1
M. E. Loman, Code 3012A4	
Air Launched Weapons Branch	
Weapons Quality Engineering Center	
CPIA, Johns Hopkins University	1
Applied Physics Lab	
John Hopkins Road, Laurel, MD 20810	
Attn: Mr. Ronald D. Brown	
Naval Plant Branch Representative	1
Attn: Mr. David W. Pratt	
P. O. Box 157, Bacchus Works	
Magna, UT 84044	

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MANPA Report Nr. 482(83)	2. GOVT ACCESSION NO. AD-A139201	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Surveillance Report, Stage I Dissected Motors, Phase		5. TYPE OF REPORT & PERIOD COVERED Test Results - Semi Annual
7. AUTHOR(s) JOHN A. THOMPSON		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Propellant Analysis Laboratory Directorate of Maintenance Hill AFB, UT 84056		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS Service Engineering Division Directorate of Materiel Management Hill AFB, UT 84056		12. REPORT DATE December 1983
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		13. NUMBER OF PAGES 120
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for Public Release, Distribution Unlimited		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Minuteman Solid Propellant		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Testing was performed to determine the useful shelf/service life for LGM-30 Stage I Rocket Motors. A three-year storage program for propellant and components was started in May 1961. This program was then extended to a ten year study and later continued indefinitely to assure that a deterioration in motor physical characteristics could be detected in time to take some corrective actions before the weapon system performance deteriorated below an acceptable level.		

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

This report covers only propellant data and limited case bond data. The malfunction of an environmental chamber destroyed component samples that had originally been part of this testing program (and the inadvertent burning of some motors during dissection reduced the material available for testing). Planned dissection of selected motors in the future will provide samples for continued component testing. Test specimens for this reporting period were obtained from motors STM-012, 0012099, and 0012199. UP-7775 block propellant was not tested since that propellant has been used up.

A new technique of Multi-symbol Regression Analysis was used to determine aging trends. Also, using a unique plotting code for each motor tested demonstrates the relationship between motors and block propellant. The plotting symbols for each motor and block propellant are listed in the statistical analyses section.

The data from this test period was combined with data from previous testing and entered into the GO85 computer for storage, analysis, and regression analysis. From the statistical analysis of all data tested to date, significant degradation of the propellant does not appear likely for at least two years past the oldest data point.

Future testing will be conducted on dissected motors.